

Date: Dec. 1, 2022

## **Important Notice to our Customers**

Product Change Notice 221201A

Re: EOL RS3, RS4, and RS+ Rheometers

### **To Our Valued Customers:**

We appreciate your use of RS3, RS4, and RS+ rheometers. The purpose of this notice is to inform you that the family of RS3, RS4, and RS+ rheometers will no longer be repaired or serviced after January 31, 2023.

#### **PCN Type:**

Notice of end of product service and life (EOL) informing customers that all repair AND calibration services for RS3, RS4, and RS+ rheometers will no longer be offered after January 31, 2023.

### **Product(s) Affected:**

RS3, RS4, and RS+ rheometers

# **Customer Impact:**

Due to the age of this product and the limited availability of components, AMETEK Brookfield will discontinue all product support, including factory calibrations, as of January 31, 2023.

AMETEK Brookfield offers products that perform similar functions as RS3, RS4, and RS+ rheometers, including the new RSX rheometer, that can be used in most instances. Please visit the AMETEK Brookfield page at www.brookfieldengineering.com for more information on our current line of viscometers and rheometers or contact AMETEK Brookfield for recommendations on alternate products.

#### Contact:

AMETEK Brookfield 11 Commerce Blvd. Middleboro, MA 02346 USA Phone: (508) 946-6200

Email: MA-MID.ccs@ametek.com