



June 6, 2017 By AMETEK Brookfield

Monitor.

Applications

## Support About Us Company History ISO 9001:2015 Search International Distributors Search th Satisfaction Survey Testimonials Archives Blog Archives Uncoming F Select Month

## • Jerome® X860-0001 860 H<sub>2</sub>S 0-200 PPM Monitor

repair services on the following instruments, effective September 1, 2017.

Jerome 860 End of Service Notification

Thank you for your support of the Jerome® 860 Hydrogen Sulfide

• Jerome® X860-0002 860 H<sub>2</sub>S 0-50 PPM Monitor

This end of service notification does not apply to the Jerome® 631-X, J605, or 651 instruments. Arizona Instrument LLC will continue to provide calibration services for all Jerome® instruments, including those covered by this end of service notification. However, if an instrument covered by this end of service notification is sent in for calibration and then found to be in need of repair, we will not be able to provide calibration services.

Due to low availability of components needed for repair, Arizona Instrument will be discontinuing

Visit our Jerome product page for more information on our latest hydrogen sulfide analyzers: the portable J605 and 631-X, as well as the stationary Jerome 651.

Thank you for your continued support. If we can help you with any questions, please  $\frac{1}{2}$ online, call us at 800.528.7411, or email us at customerservice@azic.com. Sincerely,



Rick Ervin | Vice President - Sales

Filed Under: Jerome, Latest News, Technical Notes

## Categories

Select Category

## Recent Posts

Computrac® and Jerome® Accessories Now Available Online Jerome 431-X Mercury Vapor Analyzer End of Repair Service Notice Computrac MAX-2000XL & MAX-1000 End of Life Notice





Copyright © 2020 · AMETEK Brookfield · All Rights Reserved · Sitemap · Privacy Policy · Terms and Conditions