

Service Order Work Order Report

BEL

Ametek Brookfield



SRO: [REDACTED] Description: CCS

End Date: [REDACTED]

Customer: [REDACTED] Ship To: [REDACTED]

Maint Date:

Bill To: [REDACTED]

Cust PO: [REDACTED] Ship Via: [REDACTED]

Salesperson: [REDACTED]

Line: 1 Description: [REDACTED] Unit: [REDACTED]

Item: [REDACTED] Qty: 1.00 UM: EA

Operation: 10 Operation Code: Repair Repair of Customer's Lab Equipment

General Reason: SEENOTES Specific Reason:

Received Conditions
Bent shaft.
Dirty pivot point and jewel.
Poor oscillation.
Dirty extension pin hole.

Service Performed
Cleaned Unit
Cleaned Ext. Pin Hole
Replaced Pt and Jewel
Straightened Shaft
Performed CCS
Recalibrated

Material

Trans Num	Trans Date	Item	Qty	UM
1	12/14/2017	CCS	1.00	EA
		CALIBRATION, VISCOMETER STANDARD		
2	12/14/2017	YU-1B	1.00	EA
		POINTER SHAFT BODY & CRANK ASY		
3	12/14/2017	DV-286	1.00	EA
		COUNTER WEIGHT		
4	12/14/2017	U-8B	2.00	EA

BEL

Ametek Brookfield

Service Order Work Order Report

BEL

Ametek Brookfield



POINTER BALANCE WEIGHT U-8B

5 12/14/2017

U-8A

1.00 EA

POINTER BALANCE WEIGHT U-8A

Labor

Trans Num	Trans Date	Work Code	Hours Worked
1	12/14/2017	LAB Labor Hours	1.50